

	System Sure Plus	EnSure
		
UltraSnap	1 RLU = 1 fmol ATP Pass <10; Caution 11-29; Fail 30+	1 RLU = 0.5 fmol ATP Pass <20; Caution 21-59; Fail 60+
SuperSnap	1 RLU = 0.2 fmol ATP Pass <50; Caution 51-149; Fail 150+	1 RLU = 0.1 fmol ATP Pass <100; Caution 101-299; Fail 300+



1295 Morningside Ave Units 16, 17, & 18  
 Toronto ON M1B 4Z4 Canada  
 Telephone: 416-261-4865 Fax: 416-261-7879  
[www.scigiene.com](http://www.scigiene.com)